

SB, CLUTCH DRUM, K760, K760 C-n-B, 2017-11

SYMPTOM/DESCRIPTION

In order to decrease the engine running temperature, a cooling fan is now integrated with the clutch drum.

The clutch drum is not backwards compatible without a small re-work of the crankcase:

- The fin that has been used for guiding the belt needs to be removed.
- Use a pair of pliers or a monkey wrench and break the fin along the dashed red line.



PARTS INFORMATION

Description	New P/N	Old P/N
Driving Pulley Kit	590 80 59-01	502 28 92-02

The new one will replace the old one.